



SAFETY SYSTEM
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaci, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015
UNI EN 45001:2018

Name: HUNTER boot

Code: MB3319Z9

MB33 FOOTWEAR NEW MAXIMUM SERIES

Description

High footwear made with a grain leather upper and PS-type composite midsole and fibreglass toecap. The two-component sole made of polyurethane and rubber provides a high shock-absorbing effect. The nitrile rubber tread, which is resistant to contact heat, provides a strong grip on wet surfaces, while the middle area is abrasion-resistant and equipped with cleats to increase grip on ladders. The Memory PU and polyurethane foam insole with high density and variable thickness provides a cushioning effect and ensures high shock resistance. Antistatic. The DRY PLUS tight-weave polyester lining with extra protection in the heel area has a high draining power and significantly reduces the overheating effect from prolonged use.

Main features:

- Equipped with quick-opening side zip
- Reinforced laces
- TPU overcap for increased abrasion resistance in the toe area
- Rear reinforcement for increased abrasion resistance and heel support
- Endless side grooves for drainage of liquids
- Deep, sharp-edged cleats for increased grip and self-cleaning
- Ladder Grip System (LG)
- Outsole in nitrile rubber, anti-heat, antacid, anti-oil, anti-wear, anti-drip
- Suitable for gravelly, rocky or uneven environments

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 as amended.



Category II	Colours BLACK	Available Sizes In stock: 37 - 50
Quantity/Carton 5	EC Standards EN ISO 20345 EN 61340	Important Information The footwear should be stored in a cool dry place, far from heat sources and direct light. Make sure footwear is in good condition, before use. If the shoes are damaged, replace them. Clean the footwear with a soft brush and water. The footwear should be stored in a cool dry place, far from heat sources and direct light. Make sure footwear is in good condition, before use. If the shoes are damaged, replace them. Clean the footwear with a soft brush and water.
Dexterity	Storage and cleaning	